
**EL MIRAR II
SPECIFICATION**

TYPE	Semi displacement, Twin diesel single screw yacht	
FLAG	British Virgin Islands	
DIMENSIONS	Length O.A.	33.5m (109.9ft)
	Beam	7.2m (23.5ft)
	Draft	2.3m (7.5ft)
TONNAGE	Gross	204
YEAR BUILT	2008 (refitted 2018)	
BUILDER	Horizon yachts, Taiwan	
NAVAL ARCHITECT	Horizon Yacht Works Team	
INTERIOR DESIGNER	Espinosa Yacht Design	
EXTERIOR DESIGNER	Horizon Yacht Works Team	
CONSTRUCTION	Fibreglass Hull, Fibreglass Superstructure, Teak Decks	
CLASSIFICATION	Det Norske Veritas (DNV)	

MACHINERY

MAIN ENGINES	2x Caterpillar C32-A (1,825HP each)
ENGINE HOURS	<u>November 2025:</u> <u>Port:</u> 6,577 <u>Stbd:</u> 6,572
SPEEDS & FUEL	Maximum Speed 17 knots Cruising Speed 12 knots Economical Speed 10 knots
CONSUMPTIONS	70 G/h @ 12.5 knots
RANGE	800nm @ 10 knots

AUXILIARY MACHINERY & ELECTRICAL SYSTEM

MAIN GENERATORS	2x Kohler 65kW gensets with John Deere engine
GENERATOR HOURS	<u>November 2025:</u> <u>Port: 11,958</u> <u>Starboard: 11,575</u>
BATTERIES	20 x 350AH service batteries with bar connection 4 x 200AH starting batteries for main engines with 2 x 23amp battery chargers 2 x 120AH starting batteriesfor generators with 1 x 50amp battery charger

TANK CAPACITIES (approximate)

FUEL	5,170 US Gallons (19,570 Litres)
WATER	793 US Gallons (3,000 Litres)
WATERMAKERS	Sea Recovery 1200gpd water maker
GREY WATER	300 gal
BLACK WATER	400 gal

ANCILLARY EQUIPMENT

STABILIZERS	NAIAD zero speed stabilizers
WC's	HeadHunter Tidal Wave Sanitation System
AIRCONDITIONING	Marine Air 20T chilled water A/C system

SAFETY & SECURITY EQUIPMENT

SAFETY	4x 16-person SOLAS 96 life rafts 3x EPIRBS
FIRE FIGHTING	Siemens "Flexi-Fog" fire suppression system

DECK EQUIPMENT

ANCHOR WINDLASS	2x Maxwell 4500 windlasses at bow Maxwell 3500 rope windlass at bow
GROUND TACKLE	Twin stainless steel anchors
BOAT CRANE & DAVITS	Steelhead ST2500 crane
PASSERELLE	Bensonzoni boarding passerelle

AUDIO/VISUAL ENTERTAINMENT SYSTEMS

MAIN SALON	Built in retractable 50" TV
SKYLOUNGE	40" pop-up TV
OWNERS CABIN	40" HDTV
VIP FORWARD CABIN	23" flat screen TV
MAIN DECK AFT	30" flat screen TV
BRIDGE DECK AFT	30" flat screen TV

DOMESTIC EQUIPMENT

MAIN GALLEY	GE Profile trivection oven GE Profile Advantium microwave Black & Decker 12" countertop convection oven GE Profile Quiet Power 7 dishwasher GE Profile 4-burner cooktop GE Profile Trash compactor Sub Zero full-size side by side refrigerator/freezer
CREW MESS	Sub-Zero refrigerator/freezer Kitchen Aid 2-burner cooktop GE Profile Advantium microwave
MAIN DECK AFT	U-Line ice maker Sub-zero refrigerator

BRIDGE DECK AFT	Top load freezer Sub-Zero refrigerator U-Line ice maker Wolf BBQ grille with 2 burner cooktop
SKYLOUNGE	Sub-Zero refrigerator/U-Line ice maker
SUN DECK	U-Line refrigerator/ice maker

TENDERS & WATERSPORTS EQUIPMENT

TENDERS	1x 4.57m (15ft) Zodiac (2012), 50hp Yamaha engine (2012)
WATERSPORTS/TOYS	2 story inflatable slide and 2 story inflatable climbing wall

ACCOMMODATION

Accommodation for 8 guests in 4 cabins

OWNER	1x Full beam master stateroom amidships with King Berth
GUESTS	1x VIP forward stateroom with King Berth, 1x Queen stateroom starboard side, 1x twin stateroom port side
CREW	Sleeping accommodations for a captain and three to five crew in two cabins. Captain's cabin to starboard with ensuite head and double berth, and crew stateroom to port with over/under berths and ensuite

REFIT WORKS/MAINTENANCE LIST

All soft goods, Settee's and chairs recovered. New carpet has been installed throughout. New mattresses in Master Stateroom and VIP Stateroom. New bedding throughout

2018 Refit:

FLYBRIDGE:

New Jacuzzi control panel and pumps rebuilt
Nauticomp Displays rewired and all systems operable
Updated overhead LED lights and installed dimmer

Refinished teak steps to Jacuzzi and stairs from boat deck
Installed new autopilot joystick on helm seat
New AP-70 autopilot installed
New Canopy was made
Kobelt helm pump rebuilt at drive station
All areas have been 3-step buffed

BOAT DECK:

Fiberglass repair to deck, new non-skid teak decks refinished
New LED deck lights installed plus staircase lights to flybridge
New spectra line installed on Davit
All areas 3-step buffed
Exterior house seam has been resealed
All exterior wheelhouse windows have been resealed
New Yamaha Jet Ski
Repaired Zodiac tender and rebuilt 50hp outboard engine
RTI remotes reprogrammed for AV / IT
Upgraded the breaker for all exterior deck outlets
New stern light installed

WHEELHOUSE:

Partial re-wire of the dash
All Nauticomp screens programmed for redundancy, (3) screens are new
New AP-70 autopilot
New autopilot joystick on helm chair ·Installed new A/C ducting under helm
Kobelt Steering pumps replaced
Reprogrammed Naiad program for stabilizers
Air handlers serviced
Remounted Caterpillar screens
Separated wheelhouse and boat deck outlets (each have their own breakers)
KVH and VSAT updated with new software
New Bow thruster control
New blinds on front wheelhouse windows

BOW AND MAINDECKS:

Both windlass have been completely rebuilt
New windlass control fobs installed on bulwarks
Bulwarks painted back to forward boarding doors
Bosun's locker redesigned with fishing rod-holders
New shocks on all hatches
Anchor plates re-sealed
Bow thruster oil replaced and new filter
Bow sun-cushion area has been wet sanded and buffed.
New paint on lower areas
Brand new non-skid on all decks leading to aft deck
New locks installed on galley exterior doors
All exterior windows have been resealed
New cushions on forward seating area
New LED deck lights installed
Fresh water wash down re-plumbed for anchors
Fire Pump control in bosuns locker replaced
New LED lights in bosun's locker

Both forward Glendenning's repaired
New Delta-T weather boxes installed mid-ship
New Side LED floodlights installed
All fairleads re-caulked
New control pedals for capstans and windlass
New windshield wipers

AFT DECK AND TRANSOM:

Teak decks on staircases refinished
New LED lights installed on staircases
RTI remote has been updated for AV / IT
Transom has been repainted
Transom deck fiber glass repair and new non-skid
Boarding ladder repaired
Both Glendenning's repaired
New lock installed on Transom Door plus new rubber seal
Removed faulty windlass from center of transom deck
Passerelle serviced
Both aft deck capstans rebuilt and new wiring plus foot pedals
New shocks installed on transom deck hatches
Rub rails have been re-caulked around entire boat
Hull 3-step buffed

MAIN SALON AND GALLEY:

New TV in salon
AV / IT upgraded with new software
All air handlers serviced
Main panel for all vessel lights has been simplified and dimmers installed
Fire damper actuators under windows have been replaced
Fire dampers and hinges repaired and fully operable
Dish Network boxes stacked in forward galley storage
Updated electronics
Galley stove has new control board installed
Galley fridge has new drain line
Air handlers in galley serviced
New TV in galley with RAM mount installed
New carpet throughout
New Viasat high speed Sailor 600 satellite

LOWER STATEROOMS AND BILGES:

All bilges repainted
All sump boxes have new pumps and float switches
New bilges pumps and check valves installed
Headhunter black water treatment has new pump
New Accumulator tank for black water system
New Accumulator tank for fresh water system plus individual tanks replaced for rooms
(2) new fresh water pumps plus new breaker installed
(2) new grey water pumps and check valves installed
New water heater installed under VIP
Most closets have been updated to LED lights
New Grey water tank Sentry

P-traps replaced under all stateroom sinks
LED lights installed in bilges plus New DC lights
All air handlers serviced
RTI remotes updated for new software
Washer and dryer serviced
New Master & VIP mattresses
New bedding throughout

CREW QUARTERS, RUDDER ROOM, AND CONTROL ROOM:

New black water transfer pump
All air handlers serviced
Steering rams rebuilt
Rudders have been dropped and bearings replaced
All thru hulls exercised and serviced
New live well circulation pump installed
Removed old wiring and hoses that were left from previous repairs
New pump and float switch installed in sump box
Diesel crash pump serviced
New mattress in captain's room
All (4) chillers have been serviced, plumbing and valves repaired for leaks
ASEA converters serviced
ENGINE ROOM:
Port main engine complete overhaul at 5,000 hours
Starboard main engine top end 5,000 hour service
Both transmissions serviced
Both generators top end service around 9,000 hours
Hydraulics system rebuilt (heat exchangers, filters, hoses, gear pumps, etc.)
Stabilizers dropped, new seals installed and full service, suppressors recharged
Exhausts removed and fiberglass repaired (exhaust risers repaired and serviced)
Brand new A/C fire pump
New valves on water heaters
Many hydraulic hoses replaced
Shafts pulled and checked for straightness
Props sent out to be machined
All cutlass bearings brand new
Shaft seal assemblies and all related systems new
New bottom paint and prop speed on running gear
New Zincs
New valves on main seawater manifold
New valves installed off sea chests
Steering system gone through and all necessary repairs done
Fire / safety systems certified
Rubber Heron Rib mats installed on engine room floors
All accumulator tanks for fresh water are new
Air compressor drained and serviced
Blue rope lighting repaired
New LED lights installed
Toolbox mount added above port transmission
(2) new raw water pumps installed for air conditioning system

These particulars have been prepared from information provided by the sellers and are intended as a general guide to the vessel. We cannot, however, be liable for any inaccuracy. It is up to the purchaser to confirm details of concern to him by survey, inspection and/or enquiry of the seller and to ensure that the purchase contract properly reflects his concern and specific details upon which he may rely. We always advise an independent survey.