



28 October 2020

David Miller
Sailing Vessel Jupiter 100'

Dear David,

Dive Inspection Report:

1. Zincs were in great shape with 90% life left.
2. Bottom paint in great shape with no signs of cracking or chipping.
3. Prop in great condition with no signs of warping, chipping or bends.
4. Hull shows no signs of cracks or blisters.
5. Intakes all clear.
6. Could not thoroughly inspect bow thruster due to large metal grates blocking it.
7. Significant barnacle growth on the bottom of the keel.
8. No cracks at the keeljoint.
9. No signs of corrosion.
10. Prop speed coating previously applied to prop and shaft has seriously degraded and needs to be recoated.
11. Bottom was thoroughly cleaned after inspection

Thank you,

Michelle Lessner
Owner

443-540-2287

shipsahoyinc@yahoo.com

www.shipsahoyinc.com

2501 Boston Street, Baltimore, MD 21231

