

Engine Survey

| Date: | <u>8/1/2024</u> PORT GEN | | | |
|--------------------------------|-------------------------------------|-----------------------------|-------------------------|--|
| Name of Vessel: | True Love | Type of Vessel: | Custom Aluminum Trawler | |
| Size of Vessel: | <u>73</u> | | | |
| Engine Make & Model: | Northern Lights M843NW3.3 | Engine Serial Number: | <u>8432-43342C</u> | |
| Engine Hours: | <u>6011</u> | | | |
| Trans. Make & Model: | | Trans. Serial # & Ratio: | | |
| Condition of Belts & Hoses: | Belt is cracking. Hoses look good. | | | |
| Oil or Fuel Leaks: | None found | | | |
| Coolant or Saltwater Leaks: | Seawater pump leaking at shaft seal | | | |

Coolant Freeze Point: <u>-30</u>

| Cruise | 13.5mph | FULL LOAD | 14.5mph | |
|----------------------------------|---|----------------------|---------|--|
| RPM: | 180 | <u>D</u> RPM: | | |
| Oil Pressure: | 5 | 8 Oil Pressure: | | |
| Coolant Temp: | 17 | 0 Coolant Temp: | | |
| Fuel Pressure: | n/a | Fuel Pressure: | | |
| Trans. Oil Pressure: | n/a | Trans. Oil Pressure: | | |
| Overall Condition of the Engine: | Overall unit is in very good condition. Only leak found is the seawater pump shaft seal. Recommend resealing or replacing pump. Also found some rust on the exhaust mixing elbow. Recommend further inspection. The belt is also cracking and should be replaced. Primary fuel filter is a Racor 900MA. Oil sample was good. | | | |