

Work completed since the 11/23 Survey

2/24

Dinghy outboard checked and cleaned

Engine room cleaning

Fireboy serviced Marine Survey #20b

Remove and replace courtesy lights Marine Survey #24a

Full engine and drive services both engines

Replace starboard cockpit joystick. Marine Survey item #1

Starboard main exhaust rebuild

Repair Genset leak Marine Survey item #4

New seals Forward engine hatch Marine Survey #24h

Troubleshoot and winterize water maker

New Engine exhaust valve

Installed "Hot" label Genset Exhaust Marine Survey #22

Replaced pads on ladder bases

4/25

Bottom paint done

6/25

Engine scheduled maintenance scheduled prop seals replacement

7/25

All Paint issues shown on 11/23 Survey repaired by original painter Marine Survey item #23

Documents, more details and invoices of above are all available.

Survey items