

March 28, 2016

To: Trinity Yachts / Attn: John Dane III

From: Rick Stinson / Northern Lights Gulf, Inc.

Reference: Warranty Upgrade for two (2) each 155 KW 50 Hz Generators serial # 0664-43990/0664-43991 installed in your Hull# T-056.

John,

Taking into consideration that these generators have never been commissioned but have been installed in the vessel for seven + years we suggest the services be performed as listed.

- Inspect and clean the injector pumps and injectors.
- No load running function test on the engines.
- Rebuild or replace the water pumps.
- Replace the fuel, oil and air filters.
- Conduct a megohmmeter insulation resistance test on both generators.
- Initiate a new condition warranty for both generator sets.

The services as described will cost \$12,740.00 and the price is based on the services being performed at our Northern Lights facility in Kenner, Louisiana.

The generator sets will have a one year / 2500 hour warranty from date of commissioning.

If you elect to have the services conducted on site at the Harvey Gulf Shipyard, there will be an additional cost for travel time and mileage. In addition it would be very difficult to run the engines on site without accommodations and additional costs incurred by the shipyard.

Best Regards,

Rick Stinson

Branch Manager

Northern Lights Gulf, Inc.

2:49 PM

Gmail - gensets for your vessel project.



John Dane <jdane31950@gmail.com>

gensets for your vessel project.

Jim Wilke <jimw@northern-lights.com>

Thu, Jun 2, 2022 at 8:34 PM

To: John Dane III <jdane31950@gmail.com>

Cc: Rick Stinson <rstinson@northern-lights.com>, "John F Dane" <jfdane@usmi.com>


T-056 looks like it was 130kw, 60HZ.

T-061 was 155KW, 50HZ. Trinity P.O. 766133 PO Date :Aug 08, 2008

SN Used : 0664-44997

SN Used : 0664-44998

[Quoted text hidden]

 **823270 Trinity Yachts.pdf**
1261K