Engine Survey:

Port Remarks & Recommendations:

- 1. Serviced 7-17 according to owner.
- 2. Serviceable
- 3. Transmission oil changed 8-1-18.
- 4. Serviceable
- 5. Removed corrosion, applied ospho, and protective coating. Service required on 24 volt pump.
- 6. Serviceable

Starboard Remarks & Recommendations:

- 1. Serviced 7-17 according to owner.
- 2. Serviceable
- 3. Transmission oil changed 8-1-18.
- 4. Pending
- 5. Serviceable
- 6. Serviceable
- 7. Cleaned in order to determine origin.
- 8. Serviceable

Port Generator:

- 1. Serviceable
- 2. Pending
- 3. Pending
- 4. Serviceable
- 5. Serviceable

Starboard Generator:

- 1. Pending
- 2. Cleaned in order to determine origin.
- 3. Serviceable
- 4. Serviceable
- 5. Cleaned, and Ospho applied.