

PHONE: 559-891-5499

Web: http://quinncompany.com Email: soslab@quinncompany.com

ENGINE AUX

H430-54017-4102

LABEL#: QC

SAMPLE SHIP TIME (days): 7

BUNKER A. HILL MARINE SURVEYOR LLC

RECEIVED DATE: 17-Jan-24

EQUIP NUM: AANDEEL

UIP NUM: AANDEEL





Monitor Compartment

SERIAL NUMBER: CE8094

Interp By: Tony Finney
Interpreted On: 17-Jan-24

VISCOSITY IS LOW FOR A 15W-40. FUEL TEST IS ACCEPTABLE. ALL OTHER ANALYSIS READINGS APPEAR NORMAL.

MORE SAMPLE HISTORY NEEDED TO ESTABLISH A NORMAL WEAR TREND. MONITOR FLUID LEVELS/USAGE. RESAMPLE IN 10 HOURS TO MONITOR.

SAMPLE INFORMATION

For additional sample history, go to:

S.O.S WEB

Sampled Date	10-Jan-24
Sample Id	H430-54017-4102
Lab Date	17-Jan-24
Meter [Hr]	51
Comp Meter [Hr]	51
Meter On Fluid	35
Fluid Brand	
Fluid Weight	15W-40
Fluid Type	
Fluid Change	N
Filter Change	N
Kidney Loop	U
Kidney Loop Total Fluid Added	0

CONDITION / CONTAMINATION

10-Jan-24

VISCOSITY (CENTISTOKES) ASTM D445

V100 Viscosity at 100 C 11.90

INFRARED (UFM) ASTM E2412

ST	Soot	0
OXI	Oxidation	12
SUL	Sulfur Products	16
NIT	Nitration	5

WATER

W Water

WEAR LEVELS / ADDITIVES

10-Jan-24

ELEMENTAL ANALYSIS (PPM) ASTM D5185 [OIL] / ASTM D6130 [COOLANT]				
Cu	Copper	34		
Fe	Iron	22		
Cr	Chromium	1		
Al	Aluminum	6		
Pb	Lead	0		
Sn	Tin	4		
Si	Silicon	24		
Na	Sodium	9		
K	Potassium	0		
Мо	Molybdenum	87		
Ni	Nickel	0		
Ag	Silver	0		
Ti	Titanium	0		
V	Vanadium	0		
Ca	Calcium	2860		
Р	Phosphorus	1469		
Zn	Zinc	1580		
Mg	Magnesium	487		
Ва	Barium	3		
В	Boron	85		
Sb	Antimony	0		

ANTIFREEZE

Antifreeze


FUEL

Fuel

FUEL CONTENT (%) ASTM D3524

Fc Percent Fuel 2.5





Our sample reports has been updated! For more information on the new report, go to - https://www.youtube.com/watch?v=4h8bREJVUrs