



**1005 W. STATE ROAD 84, # 511
FORT LAUDERDALE, FLORIDA 33315
Phone: 954-306-9660**

FILE NUMBER: 24595A

PREPARED FOR:

Matthew Csidai

DATE:

May 9, 2025

VESSEL NAME:

CHANTICLEER



This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

SURVEY REPORT

FILE NUMBER: 24595A

PREPARED FOR:

Matthew Csidai

DATE:

May 9, 2025

VESSEL NAME:

CHANTICLEER

GENERAL

HULL IDENTIFICATION NUMBER: 310C

DESIGNER N.A.: J. B. Hargrave

BUILDER: Burger Boat Company

BUILD #: 310C

STANDARDS: American Boat and Yacht Council

MODEL LENGTH: 108'

MODEL: Raised Pilothouse Motor Yacht

YEAR BUILT: 1973 per certificate of documentation

USCG DOCUMENTATION#: 547871

REGISTERED OWNER: no documents observed

U.S.C.G. DOCUMENT L.O.A.: 92.7' **BEAM:** 21.1' **DEPTH:** 7.5' **DRAFT:** 6.2'

REGISTERED GROSS TONS: 155

REGISTERED NET TONS: 46

GENERATOR HOURS:

PORT: 12768 on the generator hour meter

STARBOARD: 12057 on the generator hour meter

REPORTED ENGINE HOURS:

PORT: 3,795 on the engine room hour meter [3856 total hours reported]

STARBOARD: 1,999 on the engine room hour meter [4200 total hours reported]

SURVEY MADE AT: 905 Coconut Drive, Fort Lauderdale, Florida

NAVIGATIONAL LIMITS: inland, near coastal

VESSEL PURPOSE[s]: recreation

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

HULL

BOTTOM: 7/16" aluminum

CONDITION: not inspected at this time

KEEL: 3" x 36 1/2" aft end

STEM: curved

STERN: raked

FRAMES: 3" x 2" x 1/4" on 18" centers

NUMBER OF FRAMES: 65

FLOOR TIMBERS: aluminum

FASTENINGS: welds

TOPSIDES: 5/16" aluminum

CONDITION: sound

DECK BEAMS: aluminum

DECKS: 1/4" aluminum plate with teak overlay

CONDITION: See report

SUPERSTRUCTURE: aluminum

BULKHEADS: 4 full, 4 watertight to main deck

BILGE CONDITION: relatively clean

PROPELLERS: 4-bladed 40" x 40"

PROPELLER SHAFTS: 2 3/4" stainless steel **SPARE SHAFTS:** none **STUB SHAFTS:** yes

BEARINGS [SHAFT]: cutlass

STRUTS: single and double-arm each side

RUDDER: foil shaped 34" x 50"

STEERING GEAR: hydraulic

INTERIOR:

- Vinyl / wood overhead and wall covering
- Carpeted / teak & holly soles
- Mahogany trim paneling and cabinetry

MACHINERY

ENGINE MAKE: Caterpillar

ENGINE MODEL #: D3443TA

PORT ENGINE SERIAL #: 33B4724

STARBOARD ENGINE SERIAL #: 33B4723

NO. CYLINDERS: 6

RATED H.P.: 460 reported **MAXIMUM RATED R.P.M.:** 2000

YEAR: original

WHEN OVERHAULED: not reported

ENGINE SURVEY: no diesel engine surveyor was engaged for this inspection

REDUCTION GEAR: Twin Disc

RATIO: 3:1 **MODEL #:** 514

PORT SERIAL NUMBER: 388440

STARBOARD SERIAL NUMBER: 388438

ENGINE BED: aluminum stringers

PAN UNDER ENGINE: trapped area

ENGINE COOLING SYSTEM: freshwater

VENTILATION: good **BLOWER:** intake & exhaust

FILTER[s]: primary: Racor; secondary: Canister

EXHAUST LINE: hose connected; stainless steel risers

EXHAUST SILENCER: water collector-type muffler / underwater exhaust

ENGINE ALTERNATOR: 32-volt

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

CONTROLS: Glendinning electronic

SHAFTLOGS, TYPE: flex

STUFF BOX: dripless seals

WATERMAKER: Watermakers Inc.

BILGE PUMPS: 4 electric/automatic, 220-volt electric to compartment manifold

FRESHWATER PRESSURE SYSTEM: 110 VAC

AIR COMPRESSOR: 110-volt

FIRE FIGHTING & SAFETY EQUIPMENT

PORTABLE EXTINGUISHERS: Dry chemical **INSPECTION DATE:** tags September 2024

BUILT-IN SYSTEM: CO₂ **INSPECTION DATE:** tag September 2025

AUXILIARY FIRE PUMP SYSTEM: 220-volt to six fire stations

LIFE RAFT: Datrex 12-person **INSPECTION DUE:** April 2025

LIFE RAFT HYDROSTATIC RELEASE: none

LIFE JACKETS: Adult type I & II

LIFE RINGS: 30" USCG Approved

BELL: 12"

HORN: electric/ air

DISCHARGE OF OIL PLAQUE: yes

WASTE DISCHARGE PLAQUE: yes

WASTE MANAGEMENT PLAN: yes

FLARES: Orion

EXPIRATION DATE: April 2024

E.P.I.R.B: Two ACR

BATTERY EXPIRATION DATE: 2019 / 2022

E.P.I.R.B HYDROSTATIC RELEASE: none

RULES OF THE ROAD BOOK: yes

FIRST AID KIT: yes

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

ELECTRICAL SYSTEM

PORT GENERATOR: Northern Lights

LOCATION: port in the engine room

VENTILATION: good	MODEL #: M6414TQTHE-50k2	SERIAL #: 4142-8024
KILOWATTS: 50.0	VOLTAGE: 120/240	FREQUENCY: 60
NO. OF CYLINDERS: 6	RPM: 1200	COOLED: freshwater
EXHAUST LINE: hose connected fiberglass muffler FILTERS: primary: Racor		

STARBOARD GENERATOR: Northern Lights

LOCATION: starboard in the engine room

VENTILATION: good	MODEL #: M6414TQTHE-50kw	SERIAL #: 4142-8025
KILOWATTS: 50.0	VOLTAGE: 120/240	FREQUENCY: 60
NO. OF CYLINDERS: 6	RPM: 1200	COOLED: freshwater
EXHAUST LINE: hose connected fiberglass muffler FILTERS: primary: Racor		

BATTERY CHARGER[S]: 12-volt Sentry to house battery / Newmar 12-volt to generator batteries / Sentry 32-volt to house and engine batteries

LIGHTING: 32-volt D.C.

BATTERY INSTALLATION: in covered battery boxes:

- Four 8-volt lead acid to engine start
- Four 8-volt lead acid to 32-volt house service
- Two 12-volt 8D lead acid to generators
- One 12-volt to 12-volt house service

WIRING: cambric, thermoplastic, molded rubber **CONDITION:** appears good

SWITCHBOARD: engine room

FUSED: yes **CIRCUIT BREAKER:** yes **LIGHTNING ARRESTOR:** none **GROUND:** negative

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

TANKAGE

FUEL; NUMBER/CAPACITY: 3; diesel approximately 4,800 gallons total

LOCATION[s]: F33 – F49: 1500 gallons port and starboard / F33 – F49: 1800 gallons

SHAPE: integral

MATERIAL[s]: aluminum

SECURED: yes

BONDED: yes

CONDITION[s]: were not inspected internally

FILLING LINES AND VENTS: flange connected **SECURED:** yes

BONDED: yes

FUEL OVERFLOW: outboard

FUEL LINES AND CONNECTIONS: Aeroquip hose / aluminum pipe

VALVES: approved

LOCATION: aft in the engine room

ACCESSIBILITY: good

ADDITIONAL FUEL OR INFLAMMABLES CARRIED: none on-board at time of survey

WATER; NUMBER/CAPACITY: 2 approximately 2,800 gallons total

LOCATION[s]: F15 – F21: 2100 / F58 to transom 700

SHAPE: integral

MATERIAL[s]: aluminum

CONDITION[s]: were not inspected internally

HOLDING; NUMBER/CAPACITY: 1 approximately 300 gallons total

LOCATION[s]: centerline in engine room

SHAPE: integral

MATERIAL[s]: aluminum

CONDITION[s]: not inspected internally

ELECTRONICS

RADAR: Two Furuno

VHF: Icom IC-M65 . Standard Horizon Quantum

SATTV: KVH TracVision

AUTOPILOT: Simrad

GPS: Furuno nav-net

DEPTHSOUNDER: Furuno nav-net / Furuno RD30

COMPASS: Ritchie magnetic

A.I.S.: Furuno FA-150

SEARCHLIGHT: Carlisle

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

TENDER

MAKE: Nautica

MODEL: 15WB

HULL #: PTJ158145809

ENGINE[S]: Evinrude outboard **H.P.:** 90 **MODEL:** E90DSLSEB

SERIAL #: 05253410

DECK EQUIPMENT

GROUND TACKLE: Two 350-lb. Stockless anchors with approximately 300' of chain port and approximately 200' chain starboard

WINDLASS: Ideal

CLEATS: Aluminum

SAFETY RAILS: teak with aluminum stanchions

AUDIO/VIDEO

SATTV RECEIVERS: KVH Tracvision no receivers **STEREOS:** Sony

TELEVISIONS: Sharp / Sony none

HYDRAULICS

BOW THRUSTER: Wesmar

STABILIZERS: Naiad

DAVIT: Nautical Structures 2000-lb.

APPLIANCES

REFRIGERATION: U-Line / Sub-zero

ICEMAKER: U-line

STOVETOP: Wolf 4-burner electric

OVEN: Two Wolf

DISHWASHER: Frigidaire

WINE COOLER: U-Line

MICROWAVE OVEN: Panasonic

WATER HEATER: Two 40-gallon

HOT WATER CIRCULATING PUMP: yes

CLOTHES WASHER/DRYER: Miele

AIR CONDITIONING

MANUFACTURER[S]: Cruisair / Dometic chilled water **NO. OF COMPRESSORS:** Three

RAW WATER COOLING PUMPS: One **DOCKSIDE RAW WATER OPERATION CAPABILITY:** none

FRESH WATER CIRCULATION PUMPS: One

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

PHOTOGRAPHS

HULL IDENTIFICATION NUMBER

None sighted

UNITED STATES COAST GUARD OFFICIAL NUMBER

547871



This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

SALON



This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

AFT DECK



This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

DRY DOCK
JULY 31, 2023



This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

PROFILE



This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

RUNNING GEAR



This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

PREVIOUS SHELL PLATE REPLACEMENT FRESHWATER TANK



This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

EQUIPMENT

BOTTOM [ON FILE]

Bow thruster
Stabilizer fin, port and starboard
Spurs line cutters
Two underwater lights
Hull zincs

FLYBRIDGE

Surry top with aluminum frame and canvas top
Full isinglass enclosure
L-shape bench seating, port and starboard, with cushions, covers and storage
Adjustable height table, port and starboard

Wet bar, with:

- Teak countertop
- Stainless steel sink
- Faucet
- Magic Chef refrigerator
- Ice maker

Wing station, port and starboard, with:

- Glendinning controls
- Simrad jog steering control
- Rudder angle indicator
- Wesmar bow thruster control

Helm, with:

- Analog engine gauges
- Glendinning engine controls
- Ritchie compass
- Wesmar bow thruster control
- Stainless steel ships wheel
- Furuno RD30 depth sounder
- Standard Horizon VHF microphone

Marine Surveyor Group
1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

- Simrad remote autopilot control
- Furuno NavNet display

Windscreen

Triple trumpet horns

Searchlight, forward

GPS antennas

VHF radio antennas

Searchlight, port and starboard

Entry to wheel house

Fire station with spigot and hose

Clarion stereo

Badger dry chemical fire extinguisher, tag September 2024

Port and starboard navigation light

BOAT DECK

Aluminum deck with teak overlay

Datrex 12-man life raft, inspection due April 2025

Raised aluminum bulwarks with teak cap rail

Benchseat with cushions and cover, aft

Teak lounge chairs

Manual davit, starboard

Nautical Structures Euro 2000 hydraulic davit, starboard

Kitchen Aid LPG grill

LPG tank storage

Hydraulic power pack to mast for raising and lowering process

FOREDECK

Aluminum deck with teak overlay

Raised aluminum bulwarks, port and starboard

Teal cap rails

Two bow cleats

12" bell

Ideal dual anchor windlass

Watertight hatch to chain locker

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group
1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

MAIN DECK EXTERIOR

Aluminum deck with teak overlay
Raised aluminum bulwarks
Teak cap rail, port and starboard
Two spring cleats with fairleads
Two gangways, port and starboard
Entry to interior, port and starboard
Fresh water fill, starboard
Freeing ports
Aft fuel fill, port and starboard
Closed circuit television camera
24" life ring, port and starboard

COCKPIT

Aluminum deck with teak overlay
Warping winch
Transom door to swim platform
Fire station
Fresh water shower
Steps to aft deck
Teak cap rail

AFT DECK

Aluminum deck with teak overlay
Shiplap overhead
Recessed overhead lights
Door to side deck, port and starboard
Air conditioning unit, port and starboard
Spiral staircase to boat deck
Door to cockpit
Access hatch to lazarette
Two faux wicker chairs
Circular table
Sliding door to main salon
Fixed glass window, port and starboard

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group
1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

Isinglass enclosure panels, aft
Recessed overhead stereo speakers

LAZARETTE

Fresh water tank tops
Buckeye dry chemical fire extinguisher, tag September 2024
Hold light
32-volt circuit breaker panel
Two hydraulic steering actuators
Autopilot feed-back sensor
Rudder angle indicator feed-back
Blower
Four 8-volt batteries to house service
Four 8-volt batteries to engine start circuit

SALON

Mahogany sole with carpet overlay
Shiplap overhead
Recessed overhead lights
Fixed windows, port and starboard
Wood blinds
3 sofas
Table lamp
Stairwell to guest accommodations
Marine Air air conditioning control

LOWER COMPANIONWAY

Nine steps down from salon
Mahogany sole
Shiplap overhead
Recessed overhead lights
Linen locker
Fire hydrant with hose

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group
1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

PORT STATEROOM

Carpeted sole
Upholstered overhead panels
Single lower berth
Pullman berth
Vanity
Porthole with curtains
Hanging locker
Smoke alarm

STARBOARD GUEST STATEROOM

Carpeted sole
Upholstered overhead panels
Double berth
Night stand
Vanity
Porthole with curtains
Hanging locker
DirecTV receiver
Smoke alarm

AFT STATEROOM

Carpeted sole
Upholstered overhead panels
Recessed overhead lighting
Recessed stereo speakers
Queen berth with mattress and bedding
Eight drawer built-in dresser, port and starboard
Porthole with curtains, port and starboard
Hanging locker, port and starboard
Water heater in starboard locker
Vanity
Sharp LCD television
Marine Air air conditioning control

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group
1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

AFT HEAD

Tile sole
Shiplap overhead
Royal Flush toilet
Vanity with sink and faucet
Tub with tile surround
Fixed showerhead and porthole

STARBOARD HEAD

Tile sole
Shiplap overhead
Royal Flush toilet
Vanity with sink and faucet
Shower stall
Fixed showerhead and porthole

MASTER STATEROOM

Mahogany sole
Upholstered overhead panels
Recessed overhead lighting
Recessed stereo speakers
King berth with mattress and bedding
Eight drawer built-in dresser, port and starboard
Porthole with curtains, port and starboard
Hanging locker, port and starboard
Water heater in starboard locker
Vanity
Sharp LCD television
DirecTV receiver
Marine Air air conditioning control
Escape hatch
Access to shaft alleys

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group
1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

MASTER STATEROOM HEAD

Tile sole
Shiplap overhead
Dometic toilet
Vanity with sink and faucet
Shower stall
Fixed showerhead and porthole

DAY HEAD

Mahogany sole
Shiplap overhead
Vanity with custom porcelain sink
Faucet
Royal Flush head

WHEELHOUSE

Teak sole
Upholstered overhead panels
Benchseat
Two Standard Horizon Quantum VHF radios
Furuno FA150 AIS
Furuno RD 30
FLIR camera control
Manual searchlight control
Weems and Plath clock and barometer
Three Furuno displays
Two Furuno NavNet control units
VDO engine instrumentation
Two engine tachometers
Glendinning engine controls
Power steering control switches
Wesmar bow thruster control
Simrad jog steering control
Naiad stabilizer control
KVH satellite antenna control

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group
1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

Electronics circuit breaker panels
Furuno radar

HOLD BELOW WHEELHOUSE

Hold lights
Two steering pumps
Steering oil reservoir
Compressed air tank
110-volt air compressor
Power steering pump control boxes
Naiad Quantum stabilizer junction box
Fluxgate compass
Two engine room blowers
Air conditioning air handler
Amerex dry chemical fire extinguisher, tag September 2024
KVH satellite television antenna control
KVH ViaSat antenna control
Two LaMarch shore power transformers
UPS

GALLEY

Mahogany sole
Shiplap overhead
Recessed overhead lighting
Recessed overhead stereo speakers
Dinette, forward, with:

- Raised platform
- Two tables
- U-shape seating

Sony LED television
Sub-zero refrigerated drawers
Marine medical kit
Two stainless steel counter tops
Door to port side deck
Panasonic microwave oven

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group

**1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834**

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

Two burner Wolf induction stove top
Four burner Wolf stove top
Two Miele ovens
Two Sub-zero refrigerated drawers
Two Sub-zero freezer drawers
Stainless steel sink
Marine Air air conditioning control
Sub-zero under counter refrigerator
Frigidaire dishwasher

CREW QUARTERS

Vinyl sole
Shiplap overhead
Recessed overhead lights
Two portholes
Watertight door to engine room with viewing port
Seven steps down from galley
Sony LED television
U-shape settee
Table
Aqua Air air conditioning control
Norcold refrigerator
Dry chemical fire extinguisher, tag August 2023
Steps up to forward crew cabins

STARBOARD CREW CABIN

Vinyl sole
Mica overhead
Single berth with mattress
Drawers below berth
Sink with faucet

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group
1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

FORWARD CREW CABIN

Carpeted sole
Shiplap overhead
Recessed overhead lights
Escape hatch
Two portholes, port and starboard
Upper and lower single berths, port
Single berth, starboard
Four drawers, port and starboard
Hanging locker
Dry chemical fire extinguisher, tag September 2024
Fire station with spigot and hose

CREW HEAD

Parquet sole
Composite overhead
Porthole
Vanity with sink and faucet
Royal Flush toilet
Stall shower

PORT CREW CABIN

Vinyl sole
Mica overhead
Single berth with mattress
Drawers below berth
Sink with faucet
Royal Flush toilet
Stall shower

HOLD BELOW CREW QUARTERS

Hold lights
Electric/automatic bilge pump
Bow thruster

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group
1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

Miele clothes washer
Miele clothes dryer
30" life ring
Blower
Circuit panel
Fresh water system accumulator
Dry chemical fire extinguisher, tag September 2024

ENGINE ROOM

Diamond plate sole
110-volt fluorescent light
32-volt lighting
Three portholes, port
One port, starboard
Two 240-volt 100-amp shore power inlets, port
120/240-volt circuit panels with shore power/generator selector switches
Two 110-amp shore power inlet
Circuit breakers
Four tool boxes with assorted tools
Work bench with vise
Sea Recovery watermaker
Two Headhunter Mach V fresh water pumps
Stabilizer actuator, port and starboard
Marine Air air conditioning compressor to engine room
220-volt fire pump
220-volt bilge pump to compartment manifold
Air compressor
32-volt circuit breaker panel
Dual Racor fuel filter to fuel transfer system
Fuel transfer pump with meter and fuel tank valve manifold
Hersey fuel tank gauges
Hersey fresh water tank gauges
Hydraulic system oil reservoir
Black water tank
Grey water tank

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Marine Surveyor Group

**1005 W. State Road 84, # 511
Fort Lauderdale, Florida 33315
Phone: 954-612-6834**

VESSEL: CHANTICLEER
HULL #: 310C
FILE #: 24595A
DATE: May 9, 2025

Two Dometic air conditioning chillers
One Cruisair air conditioning chiller
120-240 volt air conditioning system circuit panel
Two air conditioning raw water pumps
Air conditioning chilled water loop pump
Two 12-volt lead acid batteries to generators
Newmar 12-volt charger to generator and 12-volt house service battery
12-volt battery to house service
Sentry 32-volt 30-amp charger to engine and house service batteries
Hot water heater
Water heater circulating pump
Battery cut-off switches to engines and 32-volt house service
Two Northern Light generators
Dual Racor fuel filter to each generator
Control panel to each generator
Ignition switches and gauge panels to each engine
Electric/automatic bilge pump
CO2 fire suppression system, tag September 2024
CO2 hand held fire extinguisher, tag September 2024

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.