

Engine Survey

Date:	<u>8/1/2024</u> Starboard			
Name of Vessel:	True Love	Type of Vessel:	Custom Aluminum Trawler	
Size of Vessel:	<u>73</u>			
Engine Make & Model:	Yanmar 6SY-STP2	Engine Serial Number:	<u>6516375</u>	
Engine Hours:	<u>3211</u>			
Trans. Make & Model:	<u>ZF350A</u>	Trans. Serial # & Ratio:	<u>20047197 2.630:1</u>	
Condition of Belts & Hoses:	Belt looks good. Hoses look good.			
Oil or Fuel Leaks:	None found			
Coolant or Saltwater Leaks:	Slight corrosion around the ends of the transmission cooler.			

Coolant Freeze Point: <u>-35</u>

Cruise	13.5mph	FULL LOAD	14.5mph		
RPM:	1950_RPM:		2300		
Oil Pressure:	77	Oil Pressure:	74		
Coolant Temp:	171	Coolant Temp:	189		
Fuel Pressure:	n/a	Fuel Pressure:	n/a		
Trans. Oil Pressure:	n/a	Trans. Oil Pressure:	n/a		
Overall Condition of the Engine:	Overall engine is in very good condition. Temps and pressure stayed within parameters. Saltwater does appear to be seeping from the end caps of the transmission cooler. Primary fuel filter is a racor 900MA. Engine oil sample came back good. Transmission oil sample was flagged for high water and copper. The transmission cooler could be failing and allowing water in the oil. Recommend replacing the transmission cooler and changing the oil.				