

Engine Survey

Date:	<u>8/1/2024</u> STAR GEN			
Name of Vessel:	True Love	Type of Vessel:	Custom Aluminum Trawler	
Size of Vessel:	<u>73</u>			
Engine Make & Model:	Northern Lights M944W3.3	Engine Serial Number:	<u>9442-44968C</u>	
Engine Hours:	<u>3867</u>			
Trans. Make & Model:		Trans. Serial # & Ratio:		
Condition of Belts & Hoses:	Belt is cracking. Hoses look good.			
Oil or Fuel Leaks:	None found			
Coolant or Saltwater Leaks:	None found			

Coolant Freeze Point: <u>-30</u>

Cruise	13.5mph	FULL LOAD	14.5mph	
RPM:	1800	RPM:		
Oil Pressure:	20	Oil Pressure:		
Coolant Temp:	185	Coolant Temp:		
Fuel Pressure:	n/a	Fuel Pressure:		
Trans. Oil Pressure:	n/a	Trans. Oil Pressure:		
Overall Condition of the Engine:	Overall unit is in very good condition. The belt is also cracking and should be replaced. Oil pressure seemed low. Recommend verifying with a mechanical gauge. Primary fuel filter is a Racor 900MA. Oil sample was good.			