



Blake Stahl & Associates

Marine Surveyors and Consultants

2560 SE DOWNWINDS ROAD

JUPITER, FLORIDA 33478

Phone: 561-722-1874

Blake.Stahl@Gmail.com

FILE NUMBER: 25964

PREPARED FOR:

Larry Drivon

DATE: December 8, 2023 and January 26, 2024

c/o Jeremy Floden

VESSEL NAME: NO NAME



SURVEY REPORT

FILE NUMBER: 25964

PREPARED FOR:

Larry Drivon

DATE: December 8, 2023 and January 26, 2024

c/o Jeremy Floden

VESSEL NAME: NO NAME

GENERAL

HULL IDENTIFICATION NUMBER: MCR50001K122

MANUFACTURER: Maverick Yachts S.A., Herradura, Costa Rica BUILD #: 50-001

CLASSIFICATION: none

MODEL LENGTH: 50'

CONFIGURATION MODEL: Sports Cruiser

YEAR BUILT: 2021 per hull number

MODEL YEAR: 2022 per hull number

BUILDER'S CERTIFICATE DATA: L.O.A.: 50'

BEAM: 17.04'

DRAFT: 4.2'

BALLAST: none observed

HAILING PORT: none posted

REPORTED GENERATOR HOURS: 326.3 per meter at main breaker panel

REPORTED ENGINE HOURS:

PORT: 6.2 per Garmin displays at helm

STARBOARD: 37.2 per Garmin displays at helm

SURVEY CONDUCTED: vessel's berth and Hemingway's Boatyard, 2180 Idlewilde Ct., Palm Beach Gardens, FL

VESSEL'S BERTH: North Palm Beach Marina, Slip #59, 1037 Marina Drive, North Palm Beach, FL

NAVIGATIONAL LIMITS: inland, coastwise, and Bahamas

VESSEL PURPOSE[s]: recreation

VALUES:

MARKET: approximately \$2,750,000⁰⁰ as equipped

REPLACEMENT: approximately \$3,750,000⁰⁰ as equipped

STRUCTURE

BOTTOM: cold molded Mahogany planking

CONDITION: sound

BOTTOM CONFIGURATION: Modified Vee

STEM: curved

STERN: curved

FRAMES: partitions and bulkheads

HULLSIDES: cold molded mahogany planking

CONDITION: sound

DECKS: teak plank

CONDITION: sound

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

BULKHEADS: two full; three partial

BILGE CONDITION: clean

INTERIOR:

- vinyl overhead and wall covering
- teak and holly soles
- hardwood paneling and cabinetry
- stone counters

MACHINERY

ENGINE MANUFACTURER: Volvo

ENGINE MODEL #: IPS 800

PORT ENGINE SERIAL #: 7011367390

STARBOARD ENGINE SERIAL #: 7011367353

NO. CYLINDERS: 6

RATED K.W.: 459

FULL LOAD R.P.M.: 2400

YEAR: original

OVERHAULED: xx not reported

ENGINE SURVEY: Eagle Marine

REDUCTION GEAR: IPS Pod Drive

RATIO: 1.70:1

MODEL #: IPS 2-C

PORT SERIAL NUMBER: 3950002340

STARBOARD SERIAL NUMBER: 3950002339

ENGINE BED: laminated stringers

PAN UNDER ENGINE: trapped area

ENGINE COOLING SYSTEM: raw water

VENTILATION: good **BLOWER:** yes

FILTER[s]: single Racor 1000 series

EXHAUST LINE: hose connected

EXHAUST SILENCER: underwater exhaust with side bypass

ENGINE ALTERNATOR: 24VDC

CONTROLS: electronic Volvo

SHAFTLOGS: N/A

STUFFING BOX: IPS drive flange

WATERMAKER: Watermakers Inc

BILGE PUMPS: 6 electric/automatic, 2 sump

FRESHWATER PRESSURE SYSTEM: Headhunter Mach 5

AIR COMPRESSOR: none

BOW THRUSTER: none

PROPELLERS: Volvo IPS duo-props

SPARES: none observed or reported

PROPELLER SHAFTS: stainless steel

SPARE SHAFTS: none

SHAFT BEARINGS: integral to drive pods

STRUTS: N/A

RUDDER: steerable drive pods

STEERING SYSTEM: hydraulic

FIRE FIGHTING AND SAFETY EQUIPMENT

PORTABLE EXTINGUISHERS: Dry chemical: four handheld

INSPECTION DATE: no tags

BUILT-IN SYSTEM: two 49-lb HFC-227ea in engine room

INSPECTION DATE: no tags

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

AUXILIARY FIRE PUMP SYSTEM: none

LIFE RAFT: none observed

LIFE JACKETS: assorted

BELL: N/A

DISCHARGE OF OIL PLAQUE: none observed

WASTE MANAGEMENT PLAN: none observed

FLARES: Orion

E.P.I.R.B: none observed

RULES OF THE ROAD BOOK: none observed

INSPECTION DUE: - -

LIFE RINGS: 24"

HORN: electric/air

WASTE DISCHARGE PLAQUE: no

EXPIRATION DATE: 03/25

EXPIRATION DATE: - -

FIRST AID KIT: none observed

ELECTRICAL SYSTEM

GENERATOR: Phasor

LOCATION: centerline forward in engine room

VENTILATION: good

MODEL #: K4/21/KW

SERIAL #: 08620

KILOWATTS: 21.0

VOLTAGE: 120/240

FREQUENCY: 60

CYLINDERS: 4

RPM: 1800

PHASE: 1

EXHAUST LINE: hose connected; fiberglass muffler

FILTERS: Racor 500 series

HYDRAULIC P.T.O.: no

BATTERY CHARGER[S]: Mastervolt 24VDC

LIGHTING: 12-volt D.C. and 24-volt D.C.

BATTERY INSTALLATION: in covered battery box, centerline between engines:

- Four 8D maintenance free
- One Group 31 maintenance free

WIRING: cambric, thermoplastic, molded rubber

CONDITION: good

CIRCUIT BREAKER PANELS: salon

LIGHTNING ARRESTOR: none

GROUND: negative

TANKS

FUEL; NUMBER/CAPACITY: two diesel approximately 800 gallons reported total

LOCATION[s]: 400 gallons each, port and starboard forward of engine room

SHAPE: rectangular

MATERIAL[s]: aluminum

SECURED: yes

BONDED: yes

CONDITION[s]: inaccessible

FILLING LINES AND VENTS: hose connected

SECURED: yes

BONDED: yes

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

FUEL OVERFLOW: outboard **FUEL LINES AND CONNECTIONS:** U.S.C.G. approved type A hose
VALVES: approved **LOCATION:** at filters **ACCESSIBILITY:** good
ADDITIONAL FUEL OR INFLAMMABLES CARRIED: none on-board at time of survey
FRESHWATER; NUMBER/CAPACITY: 1 approximately 200 gallons total
LOCATION[s]: athwart ship aft of aft stateroom
SHAPE: inaccessible **MATERIAL[s]:** composite
CONDITION[s]: see report
BLACK WATER; NUMBER/CAPACITY: 1 approximately 40 gallons total
LOCATION[s]: port under forward cabin sole
SHAPE: integral **MATERIAL[s]:** composite
CONDITION[s]: appears sound where accessible

ELECTRONICS

RADAR: Garmin
VHF: two Garmin **SATCOMM:** none
SATTV: KVH **AUTOPILOT:** autopilot
GPS: Garmin **P.C. PLOTTER PROGRAM:** none
DEPTHSOUNDER: Garmin
COMPASS: Ritchie magnetic
A.I.S.: none
SEARCHLIGHT: Go-Light

DECK EQUIPMENT

GROUND TACKLE: 33-lb stainless steel plow anchor with 6' of stainless steel chain and 150' of 1" nylon rode
WINDLASS: Vital Winch
CLEATS: stainless steel
SAFETY RAILS: stainless steel

AUDIO/VISUAL

SATTV RECEIVERS: KVH [antenna only] **STEREOS:** Fusion
TELEVISIONS: Samsung

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

APPLIANCES

REFRIGERATION: Isotherm

STOVETOP: 2-burner Kenyon

DISHWASHER: none

MICROWAVE OVEN: Panasonic

WATER HEATER: 24-liter Isotemp electric

CLOTHES WASHER/DRYER: none

WINE COOLER: Wine Enthusiast

AIR CONDITIONING: Webasto with FCF controls

ICEMAKER: Isotherm

OVEN: none

TRASH COMPACTOR: none

HOT WATER CIRCULATING PUMP: no

TRIAL RUN DATA

RPM	COMBINED FUEL CONSUMPTION	SPEED [MPH]
1910	40	27.8
2110	50	31.6
2370	62	38.5

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Blake Stahl & Associates
2560 SE Downwinds Road
Jupiter, Florida 33478
Phone: 561-722-1874

VESSEL: NO NAME
HULL #: MCR50001K122
FILE #: 25964
DATE: December 8, 2023 and January 26, 2024

EQUIPMENT

HARDTOP

Non-skid deck
Two stainless steel horn trumpets
Go Light remote mounted searchlight with wireless remote control
Garmin closed array radar scanner
KVH satellite television dome
Navigation lights
Volvo D.P.S. antenna
Two VHF antennas

DECKS

Teak deck
Non-skid trunk cabin with deck hatch
Frameless windows to wheelhouse
Windshield wipers with irrigators
Stainless steel handrails
Stainless steel cleats
33lb. stainless steel plow anchor with approximately 6' of stainless steel chain and 150' of 1" nylon rode
Vital Winch anchor windlass with two deck switches

AFT DECK/SWIM PLATFORM

Teak deck
Benchseating, port and starboard aft with storage
Dinette, port forward
Teak swim platform
Freshwater shower in locker, port, on swim platform
50 amp shore power inlet in locker, starboard on swim platform
Shore power main inlet breaker with ELCI circuit under starboard bench seat
Isotherm icemaker, in locker, starboard forward

LAZARETTE

Two electric/automatic bilge pumps

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Blake Stahl & Associates
2560 SE Downwinds Road
Jupiter, Florida 33478
Phone: 561-722-1874

VESSEL: NO NAME
HULL #: MCR50001K122
FILE #: 25964
DATE: December 8, 2023 and January 26, 2024

Highwater alarm
Seakeeper 9 anti-roll gyro
Electric/hydraulic pack to hatch lift

ENGINE ROOM

Entry via aft deck hatches
Two 49-lb HFC-227ea pump fixed fire suppression cylinders, no tags
Watermakers Inc. watermaker
Fiberglass muffler to generator
Headhunter Mach 5 freshwater pressure pump
24-liter Isotemp water heater
Air conditioning raw water circulating pump
Raw water cooling pump to Seakeeper
Two electric/automatic bilge pumps
Highwater alarm switch
Mastervolt 24VDC battery charger
Two Vanner battery equalizer units
Blower, port and starboard
Jabsco oil change pump
Racor 1000 series fuel filter to each engine with priming pumps
Racor 500 series fuel filter to generator
Battery box between main engines with:

- Four 8D maintenance free batteries
- One Group 31 maintenance free battery

Battery cutoff switches to:

- Port and starboard engines
- 12VDC ship's service
- 24VDC
- Generator
- Windlass

UPPER SALON

Tank and holly sole
L-shaped bench seating, port aft
Dinette with pedestal mounted table, port forward

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Blake Stahl & Associates
2560 SE Downwinds Road
Jupiter, Florida 33478
Phone: 561-722-1874

VESSEL: NO NAME
HULL #: MCR50001K122
FILE #: 25964
DATE: December 8, 2023 and January 26, 2024

Panasonic microwave on electric lift

Samsung television on electric lift

Galley counter, starboard aft with:

- Stone counters
- Kenyon 2-burner stovetop
- Isotherm refrigerated drawers
- Stainless steel sink
- Two air conditioning controllers

KVH satellite television antenna controller

Fusion stereo

Main A.C./D.C. electrical distribution panel

Professional Mariner Pro-Safe 60 galvanic isolator

BOW STATEROOM

Teak and holly sole

Vinyl overhead with recessed lights

Double island berth with storage

Electric lift to berth platform

Samsung television

FCF air conditioning controls

Hanging lockers

Orion Alert/Locate marine signal kit March 2025

24" life ring

Overhead hatch

LOWER SALON

Teak and holly sole

Vinyl overhead with recessed lights

Stone counters

Storage lockers starboard

Isotherm drawer style freezer

Dual door Wine Enthusiast wine cooler

AFT STATEROOM

Padded applied deck material

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.

Blake Stahl & Associates

2560 SE Downwinds Road

Jupiter, Florida 33478

Phone: 561-722-1874

VESSEL: NO NAME

HULL #: MCR50001K122

FILE #: 25964

DATE: December 8, 2023 and January 26, 2024

Vinyl overhead panels

Single berth, port and starboard

FCF air conditioning controls

Hanging locker with access to freshwater tank top

Samsung television

UNDER FORWARD ACCOMMODATIONS

Entry via removable ladder to aft cabin

Non-skid deck

Shower sump tank with discharge pump

Composite black water tank, port

Composite tank, starboard [plumbed to a deck fitting labeled "waste"]

Lift pump for toilet

Black water tank overboard discharge pump

Two air conditioning compressor units

Two electric/automatic bilge pumps

High water alarm switch

Condensate tank with pump

Head discharge Y-valve selector

HEAD

Teak and holly sole

Stone counter with bowl sink

Mirrored medicine locker doors

Shower stall

Blower

Headhunter toilet

This report is issued subject to the condition that it is understood and agreed that neither this office nor any surveyor nor any employee is, under any circumstance whatsoever, to be held responsible in any way for any error in judgment, default or negligence nor for any inaccuracy, omission, misrepresentation or misstatement in this report, and that the use of this report shall be construed to be an acceptance of the foregoing conditions.