

T-052 QC INSPECTION LOG

IR No.	Type Insp	Location	Status	Date	Status
STARTED		OWNER REP CLOSED AND SIGNED OFF	ABS CLOSED AND SIGNED OFF	QC INSPECTED	ABS, OWNER AND QC COMPLETE AND SIGNED OFF
100	Level	Main Deck / Jig Level Fr.3 to 45	Complete	4-Jun-2008	
101	DS	Main Deck / Beveling of plates	Started		will close with final inspection of MNDK IR#102
102	DS	Main Deck Structure Fr.3 to 45	Started		
103	DS	Crew Quarters SideShell Fr.3 to 14 P/S	Complete	13-Jan-2009	
104	DS	Fwd Guest Quarters SideShell Fr.14 to 21 P/S	Complete	18-Dec-2008	
105	DS	Aft Guest Quarters SideShell Fr.21 to 28 P/S	Complete	18-Dec-2008	
106	DS	Engine Room Side Shell Fr.28 to 37.5 P/S	Complete	14-Jan-2009	
107	DS	Lazarette SideShell Fr.37.5 to 45 P/S			
108	DS	Crew Quarters BottomShell Fr.3 to 14 P/S	Complete	13-Jan-2009	
109	DS	Fwd Guest Quarters BottomShell Fr.14 to 21 P/S	Complete	18-Dec-2008	
110	DS	Aft Guest Quarters BottomShell Fr.21 to 28 P/S	Complete	18-Dec-2008	
111	DS	Engine Room Bottom Shell Fr.28 to 37.5 P/S	Complete	14-Jan-2009	
112	DS	Lazarette BottomShell Fr.37.5 to 45 P/S	Awaiting Inspection		
113	DS	Hull module #2- Transom Fr. 46 to 48A	Complete	3-Nov-2008	
114	DS	Module #1- Guest Fuel Tanks Fr.14 to 29	Started		
114-A	Level	Module #1 Jig Fr.14 to 29	Awaiting Inspection		
114-B	DS	Module #1- prior to weld Fr.14 to 29	Awaiting Inspection		
115	DS	Module#2-Tanks/ Engine Room & Laz. Fr.29 to 43	Started		
115-A	DS	Module#2- Fitting prior to weld	Awaiting Inspection		
116	DS	Mod. 1and 2 BottomShell (Tanks) Fr.14 to 43	Started		
117	DS	Hull Module #1 Bow Fr. D to 3	Started		ABS approved Drawing Pending
118	DS	Not Used			
119	DS	Transducer Cans	Awaiting Inspection		
120	DS	Skeg Fr. 20 to41	Complete	14-Jan-2009	
121	AT	Skeg Fr. 20 to41	Started		Keel inside tanks to be tested
122	DS/AT	Dry Search & Blow test interior bulkheads	Awaiting Inspection		
123	AT	Blow test Shell Butts / Thru hull penetrations	Started		Thru hull penetrations needs inspected
124	Layout	(Location only) Main engine exhaust P/S	Awaiting Inspection		
124-A	DS/AT	Venturi Exhaust Scoop	Awaiting Inspection		
125	Layout	Location and Clocking of Stabilizers	Complete	27-Oct-2008	
126	Layout	Location and Plum of stanchions	Started		Engine Room not installed
127	AT	All intergal Tanks (Airtest)	Started		
128	DS	Rubrails	Complete	15-Dec-2008	
129	weld	" Ultrasonic Testing" shell plt.	Complete	13-Jan-2009	
130	Level	01 Deck / Jig level fr. 9 to 43	Complete		
130-A	Level	01 Deck / after rollover fr. 10 to 43	NOT USED		NOT USED
131	DS	01 Deck / Beveling of plates fr. 9 to 43	Complete	7-Aug-2008	
132	DS	01 Deck Structure fr. 9 to 43	Complete	15-Oct-2008	
132-A	DS	01 Deck beveling of Trans. Fr's 38,39,40 A &41A	Awaiting Inspection		
133	DS	01 Deck Bulwarks Fr.14 to 44	Started		ABS approved Drawing Pending
134	DS	01 Brow Fr. 2 to 14	Complete	2-Feb-2009	
135	DS	01 Deck Bulkheads Fr. 12A to 31 P/S	Started		ABS approved Drawing Pending
135-A	Align.	01 Deck Bulkheads / Window Frames P/S	Complete	23-Feb-2009	
136	Level	02 Deck /Jig Level Fr.18 to 40	Complete	21-May-2008	
136-A	Level	02 Deck after roll over Fr.18 to 40	Awaiting Inspection		
137	DS	02 Deck / Beveling of plates Fr.18 to 40	Started		
138	DS	02 Deck Structure fr. 18 to 40	Complete	20-Jun-2008	
139	DS	02 Deck Bulwarks Fr.22 A to 40	Complete	27-Oct-2008	
140	DS	02 Brow Fr. 12 to 22	Complete	27-Oct-2008	
141	DS	Rudder Room / steering systems	Awaiting Inspection		

T-052 QC INSPECTION LOG

I / R No.	Type Insp	Location	Status	Date	Status
STARTED		OWNER REP CLOSED AND SIGNED OFF	ABS CLOSED AND SIGNED OFF	QC INSPECTED	ABS, OWNER AND QC COMPLETE AND SIGNED OFF
141-A	AT	Rudder Tubes P/S	Awaiting Inspection		
141-B	AT	Rudder Fairing Log	Awaiting Inspection		
142	Layout	Port Lights P/S (Location)	Awaiting Inspection		
142-A	Align.	Port Lights P/S (Orientation)	Awaiting Inspection		
142-B	AT	Blowtest Port Lights P/S	Awaiting Inspection		
143	Fairness	Anchor Pockets (Prior to Plt.) P / S	Complete	30-Dec-2008	
200	Level	Vessel Level Fr. 3 to Fr. 45	Awaiting Inspection		
201	DS	Main Deck Bulwarks Fr. 17 to Fr. 42 P/S	Awaiting Inspection		
202	DS	Foc'sle Deck Bulwarks Fr. 0 to Fr. 17 P/S	Awaiting Inspection		
202-A	DS	Foc'sle Deck Bulwarks Fr. 0 to Fr. 17 P/S	Awaiting Inspection		
203	DS	Main Deck Bulkheads Fr. 18 to Fr. 35 P/S	Awaiting Inspection		
204	Level	Vessel Level after Superstructure Fr. 3 to Fr. 37	Awaiting Inspection		
205	DS	Main Deck Vent Trunks Fr. 32 to Fr. 37 P/S	Awaiting Inspection		
206	DS	Main Deck Wing Boards Fr. 32 to Fr. 37 P/S	Awaiting Inspection		
206-A	DS	01 Deck Wing Boards Fr. 26 to 33			
207	DS	Bosun's Locker Fr. 2A to Fr. 4	Awaiting Inspection		
208	Align.	Foc'sle Deck Window (Orientation) P/S	Awaiting Inspection		
209	Layout	Foc'sle Deck Window (Location) P/S	Awaiting Inspection		
210	Dim.	01 Deck Bulkheads/Heidi Maso Door	Awaiting Inspection		
211	DS	Transom / Swimplatform Transom Wings P/ S	Awaiting Inspection		
212	DS	Main Deck Bulkheads / window Frames	Awaiting Inspection		
213	AT	Steel Sliding Door Bhd 21	Awaiting Inspection		
214	DS	Arches and Mast	Awaiting Inspection		
214-A	AT	Arche Fuel Vent and Generator Exhaust	Awaiting Inspection		
215	DS	Main Deck insert for installing Main engines	Awaiting Inspection		
215-A	AT	Main Deck insert for installing Main engines	Awaiting Inspection		
216	AT	Watertight Door Bhd 14	Awaiting Inspection		
217	AT	Aft Strut & Shaft Log Penetration P / S	Awaiting Inspection		
217-A	Layout	Hieght of wire for propeller shaft	Awaiting Inspection		
217-B	Dim	Engine foundation P / S	Started		Prior to setting targets to weld eng. Foundations
217-C	DS	Srut Legs prior to closer plts.	Awaiting Inspection		
218	AT	Sea Chest pipe P / S	Awaiting Inspection		
219	DS	Davit Crane Foundation / Beveling	Awaiting Inspection		
219-A	Weld	NDT of Davit Crane	Awaiting Inspection		
220	DS	Generator Foundation prior to paint	Complete	16-Feb-2009	
221	AT	Hydraulic oil Independent Tank	Awaiting Inspection		
222	DS/AT	Lazzarette / Passarelle	Awaiting Inspection		
299		Keel laying Tank Module	Awaiting Inspection		