

# T-056 QC INSPECTION LOG

IR No.	Type Insp	Location	Status	Date	Status
STARTED	OWNER REP CLOSED AND SIGNED OFF	ABS CLOSED AND SIGNED OFF	QC INSPECTED	ABS, OWNER AND QC COMPLETE AND SIGNED OFF	
100	Level	Main Deck / aft Level Fr. 3 to 42	Complete	10-Dec-2007	
101	DS	Main Deck / Beveling of plates	Awaiting Inspection		
102	DS	Main Deck Structure Fr.3 to 45	Started		
103	DS	Crew Quarters SideShell Fr.3 to 14 P/S	Complete	7-Aug-2008	
104	DS	Fwd Guest Quarters SideShell Fr.14 to 21 P/S	Complete	7-Aug-2008	
105	DS	Aft Guest Quarters SideShell Fr.21 to 28 P/S	Complete	14-Aug-2008	
106	DS	Engine Room Side Shell Fr.28 to 37.5 P/S	Complete	14-Aug-2008	
107	DS	Lazarette SideShell Fr.37.5 to 45 P/S	Complete	28-Oct-2008	
108	DS	Crew Quarters BottomShell Fr.3 to 14 P/S	Complete	14-Aug-2008	
109	DS	Fwd Guest Quarters BottomShell Fr.14 to 21 P/S	Complete	14-Aug-2008	
110	DS	Aft Guest Quarters BottomShell Fr.21 to 28 P/S	Complete	23-Sep-2008	ABS approved dwg. " Pending"
111	DS	Engine Room Bottom Shell Fr.28 to 37.5 P/S	Complete	14-Aug-2008	
112	DS	Lazarette BottomShell Fr.37.5 to 45 P/S	Awaiting Inspection		
113	DS	Hull module #2- Transom Fr. 45 to 48A	Awaiting Inspection		
114	DS	Module #1- Guest Fuel Tanks Fr.14 to 28	Complete		This IR goes with # 116
114-A	Level	Module #1 Jig Fr.14 to 28	Awaiting Inspection		
114-B	DS	Module #1- prior to weld Fr. 14 to 28	Complete	8-Jan-2008	
115	DS	Module#2- Tanks/ Engine Room & Laz. Fr.28 to45	Complete	22-Feb-2008	
115-A	DS	Module#2- Fitting prior to weld			Welding started before callout
116	DS	Mod. 1 and 2 BottomShell (Tanks) Fr.14 to 45	Started		This IR goes with # 114
117	DS	Hull Module #1 Bow Fr. D to 3	Complete	14-Aug-2008	
118	DS	Not Used			
119	DS	Transducer Cans	Awaiting Inspection		
120	DS	Skeg Fr. 20 to41	Complete	7-Aug-2008	
121	AT	Skeg Fr. 20 to41	Complete	11-Nov-2008	
122	DS/AT	Dry Search & Blow test Interior bulkheads	Started		
123	AT	Blow test Shell Butts / Thru hull penetrations ( Location only )	Awaiting Inspection		
124	Layout	Layout ( Location only ) Main engine exhaust P/S	Awaiting Inspection		
124-A	DS/AT	Venturi Exhaust Scoop	Awaiting Inspection		
125	DS	Location and Clocking of Stabilizers	Started		
126	Layout	Location and Plum of stanchions	Complete	26-Feb-2008	
127	AT	All intergal Tanks ( Airtest)	Started		
128	DS	Rubralls	Complete		Transom rubrall needs inspected
129	weld	" Ultrasonic Testing" shell pit.	Complete	30-Sep-2008	
130	Level	01 Deck / Jig level fr. 9 to 43	Started		
130-A	Level	01 Deck / after rollover fr. 10 to 43	Awaiting Inspection		
131	DS	01 Deck / Beveling of plates fr. 9 to 43	Complete	27-Feb-2008	
132	DS	01 Deck Structure fr. 9 to 43	Complete	28-Jul-2008	
132-A	DS	01 Deck beveling of Trans. Fr's 38,39,40 A &41A	Complete		
133	DS	01 Deck Bulwarks Fr.14 to 43	Awaiting Inspection		
134	DS	01 Brow Fr. 3 to 14	Complete	14-Aug-2008	01 Vent trunks included in this inspection.
135	DS	01 Deck Bulkheads Fr. 12A to 31 P/S	Complete	22-Jul-2008	
135-A	Align.	01 Deck Bulkheads / Window Frames P/S	Started	14-Aug-2008	

# T-056 QC INSPECTION LOG

IR No.	Type Insp	Location	Status	Date	Status
STARTED		OWNER REP CLOSED AND SIGNED OFF	ABS CLOSED AND SIGNED OFF	QC INSPECTED	ABS, OWNER AND QC COMPLETE AND SIGNED OFF
136	Level	02 Deck/Aft Level Fr. 17 to 40	Started		
136-A	Level	02 Deck after roll over Fr. 17 to 40	Awaiting Inspection		
137	DS	02 Deck / Beveling of plates Fr. 17 to 40	Complete	18-Feb-2008	
138	DS	02 Deck Structure fr. 17 to 40	Complete	14-Mar-2008	
139	DS	02 Deck Bulwarks Fr. 21 to 40	Complete	22-Jul-2008	
140	DS	02 Brow Fr. 12 to 22	Complete	22-Jul-2008	
141	DS	Rudder Room / steering systems	Awaiting Inspection		
141-A	AT	Rudder Tubes P/S	Awaiting Inspection		
141-B	AT	Rudder Faring Log	Awaiting Inspection		
142	Layout	Port Lights P/S (Location)	Complete	30-Oct-2008	
142-A	Align.	Port Lights P/S (Orientation)	Complete	11-Nov-2008	
142-B	DS/AT	Dry Search & Blowtest Port Lights P/S	Complete	5-Dec-2008	
143	Fairness	Anchor Pockets ( Prior to Pt. ) P / S	Complete	11-Jun-2008	
200	Level	Vessel Level Fr. 3 to Fr. 45	Awaiting Inspection		
201	DS	Main Deck Bulwarks Fr. 4 to Fr. 45 P/S	Started		
202	DS	Foc'sle Deck Bulwarks Fr. 0 to Fr. 17 P/S	Not Used		See IR# 201 for inspection
202-A	DS	Foc'sle Deck Bulwarks Fr. 0 to Fr. 17 P/S	Not Used		See IR# 201 for inspection
203	DS	Main Deck Bulkheads Fr. 18 to Fr. 35 P/S	Started		
204	Level	Vessel Level after Superstructure Fr. 3 to Fr. 37	Awaiting Inspection		
205	DS	Main Deck/Vent Trunks Fr. 33 to Fr. 37 P/S	Complete	14-Jan-2009	
206	DS	Main Deck Wing Boards Fr. 32 to Fr. 37 P/S	Complete	14-Jan-2009	
206-A	DS	01 Deck Wing Boards Fr. 26 to Fr. 33 P/S	Complete	3-Sep-2008	
207	DS	Bosun's Locker Fr. 2A to Fr. 4	Awaiting Inspection		
208	Align.	Foc'sle Deck Window (Orientation) P/S	Awaiting Inspection		
209	Layout	Foc'sle Deck Window (Location) P/S	Awaiting Inspection		
210	Dim.	01 Deck Bulkheads/Heidi Maso Door	Complete	22-Jan-2009	
210-A	Dim.	Aft Main deck Cabin BHD	Complete	22-Jan-2009	
211	DS	Transom / Swimplatform Transom Wings P/S	Awaiting Inspection		
212	DS	Main Deck Bulkheads / window Frames	Awaiting Inspection		
213	AT	Steel Sliding Door Bhd 21	Awaiting Inspection		
214	DS	Arches and Mast	Complete	21-Jan-2009	
214-A	AT	Arche Fuel Vent and Generator Exhaust	Awaiting Inspection		
215	DS	Main Deck insert for installing Main engines	Complete	16-Jan-2009	
215-A	AT	Main Deck insert for installing Main engines	Complete	16-Jan-2009	
216	AT	Watertight Door Bhd 14	Awaiting Inspection		
217	AT	Aft Strut & Shaft Log Penetration P / S	Awaiting Inspection		
217-A	Layout	Hieght of wire for propeller shaft	Complete	17-Jul-2008	
217-B	Dim	Engine foundation P / S	Complete	17-Jul-2008	

# T-056 QC INSPECTION LOG

IR No.	Type Insp	Location	Status	Date	Status
STARTED		OWNER REP CLOSED AND SIGNED OFF	ABS CLOSED AND SIGNED OFF	QC INSPECTED	ABS, OWNER AND QC COMPLETE AND SIGNED OFF
217-C	DS	Grant 1000 prior to cleaver plate.	Awaiting Inspection		IR on File
218	AT	Sea Chest pipe P / S	Awaiting Inspection		
219	DS	Davit Crane Foundation / Beveling	Awaiting Inspection		
219-A	Weld	NDT of Davit Crane	Not Used		This inspection not used see IR 219
220	DS	Generator Foundation prior to paint	Complete	16-Sep-2008	
221	AT	Hydraulic Oil Independent Tank	Complete	17-Oct-2008	
222	DS/AT	Lazzarette / Passarelle	Awaiting Inspection		
223	DS/AT	Fuel Fill Containment Boxes	Awaiting Inspection		
299		Keel laying Tank Module	Awaiting Inspection		